From: BRITTAIN, ERIN

To: agremos@sbcglobal.net; Sarah Webb

Sent: 6/29/2010 2:04:11 PM
Subject: FW: Sub-slab vapor results
Attachments: DVR West Vermont St.pdf

Andy and Sarah,

Attached are the sub-slab vapor results taken at the Vermont Street homes impacted by vinyl chloride. There were several detections including PCE but no vinyl chloride.

Erin Brittain
Voluntary Remediation Program Project Manager
Indiana Department of Environmental Management
317/233-2991
ebrittai@idem.IN.gov

----Original Message----

From: HOLLAND, BILL

Sent: Thursday, June 17, 2010 12:12 PM

To: BRITTAIN, ERIN

Subject: FW: Sub-slab vapor results

Bill Holland Voluntary Remediation Program 100 North Senate Avenue MC 66-30, IGCN 1101 Indianapolis, IN 46204-2251

(317) 234-0967

(800) 451-6027 ext 4-0967

(317) 234-0428 fax

----Original Message----

From: Schlieger.Brian@epamail.epa.gov [mailto:Schlieger.Brian@epamail.epa.gov]

Sent: Thursday, April 22, 2010 3:13 PM

To: HOLLAND, BILL; ptheveno@hhcorp.org; Adam Rickert

Cc: Lam.Shelly@epamail.epa.gov
Subject: Sub-slab vapor results

Attached are the validated results of the sub-slab vapor study conducted at the three residents with the treatment systems.

The fourth sample is an ambient air sample collected from the porch of 4012 Cossell road.

ATSDR will be receiving the data for review shortly. If you have any questions please feel free to contact me.

Thanks, Brian

(See attached file: DVR West Vermont St.pdf)

Brian Schlieger On-Scene Coordinator U.S EPA 77 W. Jackson Chicago, IL 60604 Office: 312.886.0130 Cell: 734.740.9011 Fax: 312.582.5817